

CORONA IN ACCIAIO P525 - Z42 (DIS.10504)

MARCA	MODELLO	CILINDRATA	ANNI	1° EQUIP.	RIF. OEM
HONDA	CRF L Africa Twin	1000	2016 - 2019	no	
HONDA	CRF L Africa Twin	1000	2016 - 2019	no	
HONDA	CRF L Africa Twin DCT	1000	2016 - 2019	no	
HONDA	CRF L Africa Twin DCT	1000	2016 - 2019	no	
HONDA	CRF L Africa Twin	1100	2020 - 2025	no	
HONDA	CRF L Africa Twin	1100	2020 - 2025	no	
HONDA	CRF L Africa Twin Adventure / Adventure Sports	1100	2020 - 2025	no	
HONDA	CRF L Africa Twin Adventure / Adventure Sports	1100	2020 - 2025	no	
HONDA	CRF L Africa Twin Adventure DCT / CRF L Africa Twin Adventure Sports DCT	1100	2020 - 2025	no	
HONDA	CRF L Africa Twin Adventure DCT / CRF L Africa Twin Adv	1100	2020 - 2025	no	
HONDA	CRF L Africa Twin DCT	1100	2020 - 2025	no	
TRIUMPH	America Carb.	790	2003 - 2006	no	
TRIUMPH	Speedmaster	790	2003 - 2004	no	
TRIUMPH	America EFI	865	2007 - 2008	no	
TRIUMPH	America EFI	865	2007 - 2015	no	
TRIUMPH	America EFI	865	2009 - 2010	no	
TRIUMPH	America EFI	865	2011 - 2012	no	
TRIUMPH	America EFI	865	2013 - 2014	no	
TRIUMPH	BONNEVILLE AMERICA	865	2006 - 2006	no	
TRIUMPH	Speedmaster	865	2005 - 2014	no	
TRIUMPH	Speedmaster	865	2005 - 2017	no	