

## CORONA IN ACCIAIO P530 - Z43 (DIS.86601)

MARCA	MODELLO	CILINDRATA	ANNI	1° EQUIP.	RIF. OEM
TRIUMPH	Speed Triple EFI	885	1997 - 1998	no	
TRIUMPH	Speed Triple EFI	885	1997 - 1999	no	
TRIUMPH	Speed Triple EFI	885	1997 - 1999	no	
TRIUMPH	Daytona	955	1996 - 1998	no	
TRIUMPH	Daytona	955	1997 - 1998	no	
TRIUMPH	Daytona IE (Bibraccio)	955	2001 - 2001	no	
TRIUMPH	Daytona IE (Monobraccio)	955	1999 - 2000	no	
TRIUMPH	Daytona IE (Monobraccio)	955	1999 - 2000	no	
TRIUMPH	Speed Triple EFI	955	1999 - 2001	no	
TRIUMPH	Speed Triple EFI	955	1999 - 2001	no	
TRIUMPH	Sprint RS IE	955	2005 - 2005	no	
TRIUMPH	Sprint ST	955	1999 - 2004	no	
TRIUMPH	Sprint ST	955	1999 - 2004	no	
TRIUMPH	Speed Triple	1050	2011 - 2015	no	
TRIUMPH	Speed Triple	1050	2011 - 2015	no	
TRIUMPH	Speed Triple ABS	1050	2011 - 2016	no	
TRIUMPH	Speed Triple ABS	1050	2011 - 2016	no	
TRIUMPH	Speed Triple R	1050	2011 - 2015	no	
TRIUMPH	Speed Triple R	1050	2012 - 2015	no	
TRIUMPH	Speed Triple R ABS	1050	2011 - 2017	no	
TRIUMPH	Speed Triple R ABS	1050	2012 - 2017	no	
TRIUMPH	Speed Triple R ABS	1050	2018 - 2018	no	
TRIUMPH	Speed Triple R ABS	1050	2018 - 2018	no	
TRIUMPH	Speed Triple S ABS	1050	2016 - 2017	no	
TRIUMPH	Speed Triple S ABS	1050	2016 - 2017	no	
TRIUMPH	Speed Triple S ABS	1050	2018 - 2019	no	